

**RISK ASSESSMENT**

School: <i>The James Cambell Primary School</i>	Date of Trip: <i>N/A</i>
Activity: <i>Asbestos on Site</i>	Location: <i>Whole School</i>
People/Person at Risk: <i>Pupils/Staff/Visitors/Contractors</i>	Emergency Contact Details : <i>School Office 020 8270 4602/4684</i> <i>Emergency Services 999</i>
Name of Person Completing Form: Caroline Stevens	Job Title: SBM
Date: Sept 2022	Signature:
Next Review: Sept 2024	

Hazard	Risk	Initial Rating L, M, H	Existing Control Measures	Final Rating L, M, H	Additional Action Required (action by whom and completion date – use separate Action Plan if necessary)
Damage / deterioration to asbestos containing material releasing fibres into the atmosphere.	Asbestosis, mesothelioma, pleural thickening lung cancer	<i>H</i>	<ul style="list-style-type: none"> • Copy of asbestos survey, permission to work (PTW) and all related documentation retained on the school premises in the asbestos log. • All employees are aware of its location and content. • School management and asbestos authorising officers also aware of all areas which were beyond the scope of the survey e.g. ceiling voids. • No one, staff or contractors must carry out invasive work without reference to the survey. • Asbestos log is consulted at the planning stage for all projects in order location of any asbestos or areas which were not surveyed can be confirmed. • Site Supervisors, contractors and others must read and sign the PTW log before commencing any work on the fabric of the building. • All such work on fabric of building authorised by a schools 'Authorising Officer'. 	<i>L</i>	

Headteachers signatureSENCO Signature



RISK ASSESSMENT

Hazard	Risk	Initial Rating L, M, H	Existing Control Measures	Final Rating L, M, H	Additional Action Required (action by whom and completion date – use separate Action Plan if necessary)
Damage / deterioration to asbestos containing material releasing fibres into the atmosphere. Cont.....	Asbestosis, mesothelioma, pleural thickening lung cancer		<ul style="list-style-type: none">• Where there is any doubt about whether a substance or structure may contain asbestos, then no work can be undertaken. Contact the local authority• Minimum of 2 (ideally 3), authorising Officers available on site (Those conducting the work cannot authorise their own permission to work)• Refresher training undertaken by asbestos authorised officers on a 3 yearly basis.• If there is any suggestion of contamination of a particular area then (1) inform the premises manager, (2) evacuate the area, (3) seal it off and (4) contact local authority/PLT• Where ACM's have been assessed as satisfactory to leave intact an annual visual inspection of the asbestos remaining in situ is conducted by a schools authorising officer.		